## SOURCE WATER ASSESSMENT SUMMARY Amity Regional Junior High School Well #1

Well	Town	Well Type	Source Water
Location			Area (acres)
190 Luke Hill Road	Bethany	Drilled	18

Factor	Source Water Assessment Ratings For This Well	Rating
I	Environmental Sensitivity	Moderate
II	Potential Risk Factors	Low
Overall Susceptibility to Potential Sources of Contamination Low		

This rating is intended to indicate susceptibility to potential sources of contamination that may be in the wellfield source water area and does not necessarily imply poor water quality.

Ass	sessment Factors	Initial Assessment Findings	Recommendations for Enhanced Source Protection
ı	Contaminants Detected in Source Water (between 12/99 and 12/02)	Total coliform rule violation	Maintain monitoring levels specified in the Connecticut Public Health Code Section 19-13-B102
I	General condition of well and related equipment	Good	Maintain well and equipment according to best management practices
II	Number of DEP-inventoried Contaminant Release Points in Source Water Area	None	
П	Number of Potential Sources of Contamination in Source Water Area	None	
П	Land Use/Land Cover in the Well's Source Water Area (Based on Satellite Imagery developed by University of Conn.)	Commercial/Industrial 0.0% Residential 10.8% Agricultural 18.6% Open or Undeveloped 70.6%	Proactively work with local officials and developers to insure that only low risk development occurs within the source water area.  Support and encourage the acquisition of open space land within the source water area.

## **General Recommendations For All Non-community Public Water Systems**

Land Area Around Wellhead	Water system owner should provide information about the amount of land it owns or controls within a 200 foot radius around this well	
Water System Source Protection Initiatives	Water system owner should provide information about basic practices employed to protect its drinking water sources	
<b>Local Government Source Protection Initiatives</b>		

